

## MSP430F13x/14x/14x1 Device Erratasheet

### 1 Current Version

See [Appendix A](#) for prior silicon revisions.

✓ The checkmark means that the issue is present in that revision.

\* Devices with revisions marked with (\*) use BSL version 1.61. For specific information on this version of the BSL and its proper usage, see the *MSP430 Memory Programming User's Guide* ([SLAU265](#)).

Device	Rev:	ADC1	ADC5	ADC7	ADC8	ADC9	ADC10	ADC18	ADC25	BCL5	BSL3	BSL4	BSL5	CPU4	PORT3	RES3	RES4	TA12	TA16	TAB22	TB1	TB2	
MSP430F133	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F135	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F147	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1471	N									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F148	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

Device	Rev:	ADC1	ADC5	ADC7	ADC8	ADC9	ADC10	ADC18	ADC25	BCL5	BSL3	BSL4	BSL5	CPU4	PORT3	RES3	RES4	TA12	TA16	TAB22	TB1	TB2	
MSP430F1481	N								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	S								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F149	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1491	N								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*								✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

Devices	Rev:	TB2	TB3	TB4	TB14	TB16	US13	US14	US15	WDG2
MSP430F133	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F135	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F147	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1471	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F148	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1481	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F149	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1491	N	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓


## 2 Package Markings

### PAG64

#### TQFP (PAG), 64 Pin


 YMLLLLS  
 M430Fxxx  
 REV #  
 ○


 YM = Year and Month Date Code  
 LLLL = LOT Trace Code  
 S = Assembly Site Code  
 # = DIE Revision  
 o = PIN 1


 YMLLLLSG4  
 M430Fxxx  
 REV #  
 ○

 YM = Year and Month Date Code  
 LLLL = LOT Trace Code  
 S = Assembly Site Code  
 # = DIE Revision  
 o = PIN 1

### PM64

#### LQFP (PM), 64 Pin


 YMLLLLS G4  
 M430Fxxx  
 REV #  
 ○

 YM = Year and Month Date Code  
 LLLL = LOT Trace Code  
 S = Assembly Site Code  
 # = DIE Revision  
 o = PIN 1

### RTD64

#### QFN (RTD), 64 Pin

 ○ M430Fxxx  
  
 TI YMS  
 LLLL #

 TI = TI  
 YM = Year and Month Date Code  
 LLLL = LOT Trace Code  
 S = Assembly Site Code  
 # = DIE Revision  
 o = PIN 1

 ○ M430Fxxx  
  
 TI YMSG3  
 LLLL #

 TI = TI  
 YM = Year and Month Date Code  
 LLLL = LOT Trace Code  
 S = Assembly Site Code  
 # = DIE Revision  
 o = PIN 1

### 3 Detailed Bug Description

<b>ADC1</b>	<b><i>ADC12 Module</i></b>
<b>Function</b>	Start of conversion
<b>Description</b>	In single conversion/sequence mode (CONSEQ = 0/1), the next conversion can be started with ADC12SC. It is not necessary to clear ENC before setting ADC12SC. This is contrary to the specification.
<b>Workaround</b>	None
<b>ADC5</b>	<b><i>ADC12 Module</i></b>
<b>Function</b>	Interrupt flag register
<b>Description</b>	ADC12 interrupt flag may not be set when the CPU simultaneously accesses the ADC12IFG register.
<b>Workaround</b>	There is no need to access the interrupt flag register to process interrupt situations. Use the ADC12IV register to identify the interrupt event. The corresponding flag bits are reset automatically. Additional details are discussed in the device family user's guide.
<b>ADC7</b>	<b><i>ADC12 Module</i></b>
<b>Function</b>	Conversion time overflow
<b>Description</b>	The timing overflow flag is set when the device is in sequence mode (CONSEQ = 1 or 3) and MSC = 0, even if no overflow has occurred.
<b>Workaround</b>	Verify correct timing and do not enable Conversion-Time Overflow interrupt.
<b>ADC8</b>	<b><i>ADC12 Module</i></b>
<b>Function</b>	Interrupt flag register
<b>Description</b>	Clearing flags in the interrupt flag register with a CPU instruction does not clear the latest interrupt flag.
<b>Workaround</b>	Clear interrupt flags by accessing the conversion memory registers.
<b>ADC9</b>	<b><i>ADC12 Module</i></b>
<b>Function</b>	Interrupt vector register
<b>Description</b>	If the ADC12 uses a different clock than the CPU (MCLK) and more than one ADC interrupt is enabled, the ADC12IV register content may be unpredictable for one clock cycle. This happens if, during the execution of an ADC interrupt, another ADC interrupt with higher priority occurs.
<b>Workaround</b>	<ul style="list-style-type: none"> <li>• Read out ADC12IV twice and use only when values are equal.</li> <li>or</li> <li>• Use ADC12IFG to determine which interrupt has occurred.</li> </ul>

<b>ADC10</b>	<b>ADC12 Module</b>
<b>Function</b>	Unintended start of conversion
<b>Description</b>	Accessing ADC12OVIE or ADC12TOVIE at the end of an ADC12 conversion with BIS/BIC commands can cause the ADC12SC bit to be set again immediately after it was cleared. This might start another conversion, if ADC12SC is configured to trigger the ADC (SHS = 0).
<b>Workaround</b>	If ADC12SC is configured to trigger the ADC, the control bits ADC12OVIE and ADC12TOVIE should be modified only when the ADC is not busy (ADC12BUSY = 0).
<b>ADC18</b>	<b>ADC12 Module</b>
<b>Function</b>	Incorrect conversion result in extended sample mode
<b>Description</b>	The ADC12 conversion result can be incorrect if the extended sample mode is selected (SHP = 0), the conversion clock is not the internal ADC12 oscillator (ADC12SSEL > 0), and one of the following two conditions is true: <ul style="list-style-type: none"> <li>• The extended sample input signal SHI is asynchronous to the clock source used for ADC12CLK and the undivided ADC12 input clock frequency exceeds 3.15 MHz.</li> <li>or</li> <li>• The extended sample input signal SHI is synchronous to the clock source used for ADC12CLK and the undivided ADC12 input clock frequency exceeds 6.3 MHz.</li> </ul>
<b>Workaround</b>	<ul style="list-style-type: none"> <li>• Use the pulse sample mode (SHP = 1).</li> <li>or</li> <li>• Use the ADC12 internal oscillator as the ADC12 clock source.</li> <li>or</li> <li>• Limit the undivided ADC12 input clock frequency to 3.15 MHz.</li> <li>or</li> <li>• Use the same clock source (such as ACLK or SMCLK) to derive both SHI and ADC12CLK, to achieve synchronous operation, and also limit the undivided ADC12 input clock frequency to 6.3 MHz.</li> </ul>
<b>ADC25</b>	<b>ADC12 Module</b>
<b>Function</b>	Write to ADC12CTL0 triggers ADC12 when CONSEQ = 00
<b>Description</b>	If ADC conversions are triggered by the Timer_B module and the ADC12 is in single-channel single-conversion mode (CONSEQ = 00), ADC sampling is enabled by write access to any bit(s) in the ADC12CTL0 register. This is contrary to the expected behavior that only the ADC12 enable conversion bit (ADC12ENC) triggers a new ADC12 sample.
<b>Workaround</b>	When operating the ADC12 in CONSEQ = 00 and a Timer_B output is selected as the sample and hold source, temporarily clear the ADC12ENC bit before writing to other bits in the ADC12CTL0 register. The following capture trigger can then be re-enabled by setting ADC12ENC = 1.

<b>BCL5</b>	<b><i>Basic Clock Module</i></b>
<b>Function</b>	RSELx bit modifications can generate high-frequency spikes on MCLK
<b>Description</b>	When DIVMx = 00 or 01, the RSELx bits of the Basic Clock module are incremented or decremented in steps of 2 or greater, the DCO output may momentarily generate high-frequency spikes on MCLK, which may corrupt CPU operation. This is not an issue when DIVMx = 10 or 11.
<b>Workaround</b>	Set DIVMx = 10 or 11 to divide the MCLK input prior to modifying RSELx. After the RSELx bits are configured as desired, the DIVMx setting can be changed back to the original selection.
<b>BSL3</b>	<b><i>Bootstrap Loader Module</i></b>
<b>Function</b>	Receiving frames
<b>Description</b>	Receiving frames with a checksum value equal to a legal address can change the content of this address or the bootstrap loader may stop operation.
<b>Workaround</b>	Software workaround is available.
<b>BSL4</b>	<b><i>Bootstrap Loader Module</i></b>
<b>Function</b>	Flash memory cannot be programmed
<b>Description</b>	The bootstrap loader software cannot program the flash memory.
<b>Workaround</b>	Software workaround is available.
<b>BSL5</b>	<b><i>Bootstrap Loader Module</i></b>
<b>Function</b>	$\overline{\text{RST}}$ /NMI configured as NMI
<b>Description</b>	If the $\overline{\text{RST}}$ /NMI pin is configured to NMI, the bootstrap loader may not be started. Unpredictable operation results.
<b>Workaround</b>	None
<b>CPU4</b>	<b><i>CPU Module</i></b>
<b>Function</b>	PUSH #4, PUSH #8
<b>Description</b>	The single operand instruction PUSH cannot use the internal constants (CG) 4 and 8. The other internal constants (0, 1, 2, -1) can be used. The number of clock cycles is different: PUSH #CG uses address mode 00, requiring 3 cycles, 1-word instruction PUSH #4/#8 uses address mode 11, requiring 5 cycles, 2-word instruction
<b>Workaround</b>	Workaround implemented in assembler. No fix planned.

<b>PORT3</b>	<b><i>Digital I/O Module, Port 1/2</i></b>
<b>Function</b>	Port interrupts can be lost
<b>Description</b>	Port interrupts can be lost if they occur during CPU access of the P1IFG and P2IFG registers.
<b>Workaround</b>	None
<b>RES3</b>	<b><i>General, Reset</i></b>
<b>Function</b>	Reset
<b>Description</b>	When $\overline{\text{RST/NMI}}$ is held low during power up of $V_{\text{CC}}$ , some internal drivers are not reset correctly. This may result in a high $I_{\text{CC}}$ current until the internal power-on signal has generated one clock cycle to reset the internal drivers. This limits the time when the excess current can occur to the time the power-up circuit is active.
<b>Workaround</b>	None
<b>RES4</b>	<b><i>General, Reset</i></b>
<b>Function</b>	No reset if external resistor exceeds certain value
<b>Description</b>	No reset of the device is performed if the external pulldown resistor on $\overline{\text{RST/NMI}}$ pin is above a certain limit. The limits are: $V_{\text{CC}} = 1.8 \text{ V}$ : maximum pulldown resistor = 12 k $\Omega$ $V_{\text{CC}} = 3.0 \text{ V}$ : maximum pulldown resistor = 5 k $\Omega$ $V_{\text{CC}} = 3.6 \text{ V}$ : maximum pulldown resistor = 2.5 k $\Omega$ In addition, a higher current consumption occurs during high/low $\overline{\text{RST/NMI}}$ signal transition when using improper resistors.
<b>Workaround</b>	Use external pulldown resistors below the listed values or directly drive $\overline{\text{RST/NMI}}$ low to generate a reset.
<b>TA12</b>	<b><i>Timer_A Module</i></b>
<b>Function</b>	Interrupt is lost (slow ACLK)
<b>Description</b>	Timer_A counter is running with slow clock (external TACLK or ACLK) compared to MCLK. The compare mode is selected for the capture/compare channel and the CCRx register is incremented by one with the occurring compare interrupt (if $\text{TAR} = \text{CCRx}$ ). Due to the fast MCLK, the CCRx register increment ( $\text{CCRx} = \text{CCRx} + 1$ ) happens before the Timer_A counter has incremented again. Therefore, the next compare interrupt should happen at once with the next Timer_A counter increment (if $\text{TAR} = \text{CCRx} + 1$ ). This interrupt is lost.
<b>Workaround</b>	Switch capture/compare mode to capture mode before the CCRx register increment. Switch back to compare mode afterward.



<b>TA16</b>	<b><i>Timer_A Module</i></b>
<b>Function</b>	First increment of TAR erroneous when IDx > 00
<b>Description</b>	The first increment of TAR after any timer clear event (POR/TACLR) happens immediately following the first positive edge of the selected clock source (INCLK, SMCLK, ACLK, or TACLK). This is independent of the clock input divider settings (ID0, ID1). All following TAR increments are performed correctly with the selected IDx settings.
<b>Workaround</b>	None
<b>TAB22</b>	<b><i>Timer_A/Timer_B Module</i></b>
<b>Function</b>	Timer_A/B register modification after Watchdog Timer PUC
<b>Description</b>	Unwanted modification of the Timer_A/B registers TACTL and TAIV can occur when a PUC is generated by the Watchdog Timer (WDT) in watchdog mode and any Timer_A/B counter register TACCRx/TBCCRx is incremented/decremented (Timer_A/B does not need to be running).
<b>Workaround</b>	Initialize TACTL/TBCTL register after the reset occurs using a MOV instruction (BIS/BIC may not fully initialize the register). TAIV/TBIV is automatically cleared following this initialization.  <b>Example code:</b> <pre>MOV.W #VAL, &amp;TACTL</pre> or <pre>MOV.W #VAL, &amp;TBCTL</pre> Where, VAL = 0, if Timer is not used in application; otherwise, user defined per desired function.
<b>TB1</b>	<b><i>Timer_B Module</i></b>
<b>Function</b>	"Equal mode" when grouping compare latches
<b>Description</b>	The "equal mode" for loading the compare latches (CLLD = 3) cannot be used when compare latches are grouped (TBCLGRP > 0).
<b>Workaround</b>	None
<b>TB2</b>	<b><i>Timer_B Module</i></b>
<b>Function</b>	Interrupt is lost (slow ACLK)
<b>Description</b>	Timer_B counter is running with slow clock (external TBCLK or ACLK) compared to MCLK. The compare mode is selected for the capture/compare channel and the CCRx register is incremented by 1 with the occurring compare interrupt (if TBR = CCRx).  Due to the fast MCLK, the CCRx register increment (CCRx = CCRx + 1) happens before the Timer_B counter has incremented again. Therefore, the next compare interrupt should happen at once with the next Timer_B counter increment (if TBR = CCRx + 1). This interrupt is lost.
<b>Workaround</b>	Switch capture/compare mode to capture mode before the CCRx register increment. Switch back to compare mode afterward.

**TB3** *Timer\_B Module*


**Function** Port is switched to 3-state independent of selected function

**Description** Incorrect 3-state function of Ports P4.0/TB0 through P4.6/TB6 (TBoutHiZ control). If TBoutHiZ is set to high, all ports P4.0/TB0 through P4.6/TB6 are set to 3-state, independent of the P4SEL.x control signals. This means a port P4.x is switched to 3-state with TBoutHiZ, even if it is not selected for Timer\_B function. In addition, the ports P4.0/TB0 through P4.6/TB6 are switched to 3-state with TBoutHiZ, even if the port direction (direction control from module) is set to input. This is in accordance with the specification description but, nevertheless, is an unexpected behavior.


**Workaround** None

**Port Function as Specified**

port P4, P4.0 to P4.6, input/output with Schmitt-trigger


**Port Realization With TB3 Bug**

port P4, P4.0 to P4.6, input/output with Schmitt-trigger



**TB4**

**Timer\_B Module**

**Function**

Group function

**Description**

If the shadow registers are organized in groups (SHR = 1, 2, or 3), one shadow register is not loaded correctly. This happens when the last CCRx register within a group is loaded at exactly the same time that the timer counter reaches the event for loading the shadow registers (TBR = 0 or TBR = CCR0).

**Workaround**

Ensure that all CCRx registers within a group are loaded before the shadow register load event occurs.

**TB14**

**Timer\_B Module**

**Function**

PWM output

**Description**

The PWM output unit may behave erroneously if the condition for changing the PWM output (EQUx or EQU0) and the condition for loading the shadow register TBCLx happen at the same time. Depending on the load condition for the shadow registers (CLLD bits in TBCCTLx), there are four possible error conditions:

1. Change CCRx register from any value to CCRx = 0 (for example, sequence for CCRx = 4 3 2 0 0 0)
2. Change CCRx register from CCRx = 0 to any value (for example, sequence for CCRx = 0 0 0 2 3 4)
3. Change CCRx register from any value to current SHD0 (CCR0) value (for example, sequence for CCRx = 4 2 5 SHD0 3 8)
4. Change CCRx register from current SHD0 (CCR0) value to any value (for example, sequence for CCRx = 4 2 SHD0 5 3 8)

**Workaround**

No general workaround available

<b>TB16</b>	<b><i>Timer_B Module</i></b>
<b>Function</b>	First increment of TBR erroneous when IDx > 00
<b>Description</b>	The first increment of TBR after any timer clear event (POR/TBCLR) happens immediately following the first positive edge of the selected clock source (INCLK, SMCLK, ACLK, or TBCLK). This is independent of the clock input divider settings (ID0, ID1). All following TBR increments are performed correctly with the selected IDx settings.
<b>Workaround</b>	None
<b>US13</b>	<b><i>USART0, USART1 Module</i></b>
<b>Function</b>	Unpredictable program execution
<b>Description</b>	USART interrupts requested by URXS can result in unpredictable program execution if this request is not served within two bit times of the received data.
<b>Workaround</b>	Ensure that the interrupt service routine is entered within two bit times of the received data.
<b>US14</b>	<b><i>USART0, USART1 Module</i></b>
<b>Function</b>	Lost character start edge
<b>Description</b>	When using the USART in UART mode with UxBR0 = 0x03 and UxBR1 = 0x00, the start edge of received characters may be ignored due to internal timing conflicts within the UART state machine. This condition does not apply when UxBR0 > 0x03.
<b>Workaround</b>	None
<b>US15</b>	<b><i>USART0, USART1 Module</i></b>
<b>Function</b>	UART receive with two stop bits
<b>Description</b>	USART hardware does not detect a missing second stop bit when SPB = 1. The framing error flag (FE) is not set under this condition, and erroneous data reception may occur.
<b>Workaround</b>	None (configure USART for a single stop bit, SPB = 0)
<b>WDG2</b>	<b><i>Watchdog Module</i></b>
<b>Function</b>	Incorrectly accessing a flash control register
<b>Description</b>	If a key violation is caused by incorrectly accessing a flash control register, the watchdog interrupt flag is set in addition to a correctly generated PUC.
<b>Workaround</b>	None

## Appendix A Prior Versions

✓ The checkmark means that the issue is present in that revision.

\* Devices with revisions marked with (\*) use BSL version 1.61. For specific information on this version of the BSL and its proper usage, see the *Memory Programming User's Guide* ([SLAU265](#)).

Device	Rev:	ADC1	ADC5	ADC7	ADC8	ADC9	ADC10	ADC11	ADC18	ADC25	BCL5	BSL3	BSL4	BSL5	CPU4	PORT3	RES3	RES4	TA12	TA16	TAB22
MSP430F133	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F135	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F147	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1471	L									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

Device	Rev:	ADC1	ADC5	ADC7	ADC8	ADC9	ADC10	ADC11	ADC18	ADC25	BCL5	BSL3	BSL4	BSL5	CPU4	PORT3	RES3	RES4	TA12	TA16	TAB22	
MSP430F148	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	M	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	N	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Q	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	O	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	S	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1481	L									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	M									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	N									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Q									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	O									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	S									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AA*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AB*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AD*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AE									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
MSP430F149	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	M	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	N	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Q	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	O	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	S	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AA*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AB*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AD*	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AE	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
MSP430F1491	L									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	M									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	N									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	Q									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	O									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	S									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AA*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AB*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AD*									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
	AE									✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	

Device	Rev:	TB1	TB2	TB3	TB4	TB14	TB16	US13	US14	US15	WDG2
MSP430F133	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F135	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F147	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1471	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓

Device	Rev:	TB1	TB2	TB3	TB4	TB14	TB16	US13	US14	US15	WDG2
MSP430F148	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1481	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F149	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
MSP430F1491	L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	M	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	N	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	Q	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	O	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	S	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AA*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AB*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AD*	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	AE	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓



**A.1 Detailed Bug Description****ADC11*****ADC12 Module***

---

**Function**

Temporary leakage current after conversion

**Description**

The ADC12 causes temporary leakage current after a completed conversion. Duration and magnitude of the leakage current depends on parasitic effects.

**Workaround**

None

---

## Revision History

<b>Changes from D Revision (May 2010) to E Revision</b>	<b>Page</b>
• Added silicon revisions AD and AE to Current Version table; revisions AA, AB, AD marked with BSL version 1.61. ....	1
• Added silicon revisions AD and AE to Prior Versions table; revisions AA, AB, AD marked with BSL version 1.61. ....	13

---

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

## IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

<b>Products</b>		<b>Applications</b>	
Amplifiers	<a href="http://amplifier.ti.com">amplifier.ti.com</a>	Audio	<a href="http://www.ti.com/audio">www.ti.com/audio</a>
Data Converters	<a href="http://dataconverter.ti.com">dataconverter.ti.com</a>	Automotive	<a href="http://www.ti.com/automotive">www.ti.com/automotive</a>
DLP® Products	<a href="http://www.dlp.com">www.dlp.com</a>	Communications and Telecom	<a href="http://www.ti.com/communications">www.ti.com/communications</a>
DSP	<a href="http://dsp.ti.com">dsp.ti.com</a>	Computers and Peripherals	<a href="http://www.ti.com/computers">www.ti.com/computers</a>
Clocks and Timers	<a href="http://www.ti.com/clocks">www.ti.com/clocks</a>	Consumer Electronics	<a href="http://www.ti.com/consumer-apps">www.ti.com/consumer-apps</a>
Interface	<a href="http://interface.ti.com">interface.ti.com</a>	Energy	<a href="http://www.ti.com/energy">www.ti.com/energy</a>
Logic	<a href="http://logic.ti.com">logic.ti.com</a>	Industrial	<a href="http://www.ti.com/industrial">www.ti.com/industrial</a>
Power Mgmt	<a href="http://power.ti.com">power.ti.com</a>	Medical	<a href="http://www.ti.com/medical">www.ti.com/medical</a>
Microcontrollers	<a href="http://microcontroller.ti.com">microcontroller.ti.com</a>	Security	<a href="http://www.ti.com/security">www.ti.com/security</a>
RFID	<a href="http://www.ti-rfid.com">www.ti-rfid.com</a>	Space, Avionics & Defense	<a href="http://www.ti.com/space-avionics-defense">www.ti.com/space-avionics-defense</a>
RF/IF and ZigBee® Solutions	<a href="http://www.ti.com/lprf">www.ti.com/lprf</a>	Video and Imaging	<a href="http://www.ti.com/video">www.ti.com/video</a>
		Wireless	<a href="http://www.ti.com/wireless-apps">www.ti.com/wireless-apps</a>